

RFI's VA261-14-R-0583: Amico 15-H-2 Steel Grating System

1. Please clarify that existing chipped concrete areas do not need to be repaired.

VA Response: Existing chipped concrete does need to be repaired

2. Does the VA have As-built section detail of the existing concrete trench to verify concrete ledge capacity for proposed steel Grates that can be provided to the bidding contractors.

VA Response: See attached Drawing "Pipe Tunnel Modifications".